

Phoenix Capabilities List

Base Part Number	Subassembly Part Number	Model Number	Description	Manufacturer
4052190-9XX			TCAS Control Panel	ACSS or Honeywell International Inc
4061400-9XX			Mode S Transponder	ACSS or Honeywell International Inc
	4061412-9XX		Motherboard	ACSS or Honeywell International Inc
	4061409-9XX		Power Supply	ACSS or Honeywell International Inc
	4067465-9XX		Processor	ACSS or Honeywell International Inc
	4061442-9XX		Interface	ACSS or Honeywell International Inc
	7514150-9XX		Receiver I/O	ACSS or Honeywell International Inc
	7514153-9XX		Transmitter	ACSS or Honeywell International Inc
4066010-9XX		TCAS II	TCAS II Computer Unit	ACSS or Honeywell International Inc
	4066011-9XX		Chassis	ACSS or Honeywell International Inc
	4066017-XXXX		CAS CCA	ACSS or Honeywell International Inc
	4066019-XXXX		SURV CCA	ACSS or Honeywell International Inc
	4066021-9XX		Power Supply	ACSS or Honeywell International Inc
	7514216-9XX		I/O Module	ACSS or Honeywell International Inc
	7514217-9XX		Receiver Module	ACSS or Honeywell International Inc
	7514218-9XX		Transmitter Module	ACSS or Honeywell International Inc
4067241-8XX		VSI/TRA	Display Indicator	ACSS or Honeywell International Inc
4067487-901		PTM	Pressure Transducer Module	ACSS or Honeywell International Inc
7510700-850		RCZ-852	Mode S Transponder	ACSS or Honeywell International Inc

## REPAIR STATION

Base Part Number	Subassembly Part Number	Model Number	Description	Manufacturer
7510700-9XX		RCZ-852	Mode S Transponder	ACSS
	7517400-905		RCZ-852 Transponder SRU	ACSS or Honeywell International Inc
	7517400-501		RCZ-852 Change 7 Transponder SRU	ACSS
7514060-9XX		TCAS Antenna	TCAS Antenna	ACSS or Honeywell International Inc
7514081-9XX		TCAS Antenna	TCAS Antenna	ACSS or Honeywell International Inc
7517800-XXXXX		XS-950	ATDL	ACSS or Honeywell International Inc
	7517820-902		Interconnect Assembly	ACSS or Honeywell International Inc
	7517826-XXX		ATDL Processor CCA	ACSS or Honeywell International Inc
	7517830-XXX		ATDL Power Supply	ACSS or Honeywell International Inc
	7517835-XXX		ATDL TX/RX Module	ACSS or Honeywell International Inc
	7517839-901		Russian version Power Supply	ACSS or Honeywell International Inc
7519350-XXXXX		XS-950S/I	ATDL/IFF	ACSS or Honeywell International Inc
	7517826-942		ATDL/IFF Processor CCA	ACSS or Honeywell International Inc
	7517830-XXX		ATDL Power Supply	ACSS or Honeywell International Inc
	7517835-XXX		ATDL TX/RX Module	ACSS or Honeywell International Inc
7517900-XXXXX		RT-950	TCAS 2000 Computer Unit	ACSS or Honeywell International Inc
	7517920-9XX		Interconnect Assembly	ACSS or Honeywell International Inc
	7517923-9XX		Spectrum Filter Assembly	ACSS or Honeywell International Inc
	7517925-9XX		TCAS Processor Assembly	ACSS or Honeywell International Inc

## REPAIR STATION

Base Part Number	Subassembly Part Number	Model Number	Description	Manufacturer
	7517930-9XX		TCAS Power Supply Module	ACSS or Honeywell International Inc
	7517935-9XX		TCAS Transmitter Module	ACSS or Honeywell International Inc
	7517945-9XX		TCAS Receiver Module	ACSS or Honeywell International Inc
9000000-XXXXX		TT-95X	T2CAS	ACSS
	9000020-XXX		T2CAS TAWS Assembly	ACSS
	9000005-XXX		T2CAS Interconnect	ACSS
	9000010-XXX		T2CAS Interconnect	ACSS
	9000015-XXX		T2CAS Power Supply	ACSS
	9000025-XXX		T2CAS GPS Receiver	ACSS
9000001-XXXXX		AP-950	Aircraft Personality Module	ACSS

**REVISION HISTORY**

Revision	Date of Revision	Description of Change
Rev -	01/30/04	<b>ECR007282</b> - Initial Release Author – Kevin Murtagh (PRO), Repair and Overhaul and Bobby Scott, Quality and Process Assurance (DDI)
Rev A	04/05/04	<b>ECR00xxxx</b> – Added Subassembly P/N 7517400-501. Revised by Kevin Murtagh (PRO) Repair Station Manager

**END OF DOCUMENT**